#### **BELVEDERE CLUB 2019 ARCHITECTURAL INVENTORY**



Site: 25 Historic Name N/A

### Year Built c. 1890 Architectural Style Shingle style

The two-story cottage has narrow clapboard siding at the first floor and shingle siding at the second floor, the shingles typical of the Shingle style. The first and second floor porches are seen on seaside examples of the style and the lunette in the gable dormer with Colonial Revival details is another characteristic feature. The first and second story porches originally had paired Doric columns supported by a shingle knee wall with railings in between. There was an internal cobblestone chimney in the north gable that has been replaced with an external brick chimney. The original two-over-two windows have been replaced with one-over-one windows.

### **Significant Features**

- Narrow clapboard and shingle siding.
- Colonial Revival detailed lunette in the gable front dormer.
- First and second story front porches.
- Window arrangement, including the bay window on the first floor.
- Deep overhangs and gable roof.

### Condition

The cottage is in good repair no issues are apparent.

#### BELEVEDERE CLUB 2019 ARCHITECTURAL SURVEY

#### **ADDITIONAL PHOTOS**

# 1907 and 1916 photos



# 2019 –South and east



East



# West and south

