

BELVEDERE CLUB 2019 ARCHITECTURAL INVENTORY



Site: 43

Historic Name N/A

Year Built c. 1900

Architectural Style Shingle style

The large side gambrel roof with both hip roof and gable front flared wall dormers clad in shingles along with the narrow clapboard at the first floor and shingles at the second floor, complete with a wavy wall surface and row of windows in the gable ends are indicative of the Shingle style. The full width front porch under an extension of the main roof supported by Doric pillars as well as the windows with the multiple panes in the upper sash are also indicative of the style.

Significant Features

- Side gambrel roof with hipped roof flared wall and gambrel front dormers with shingle siding.
- Narrow clapboard siding at the first floor with shingle siding at the second floor.
- Windows with multiple panes in the upper sash.
- Full width front porch under an extension of the main roof supported by Doric pillars and central stair.
- Recessed rear porch.

Condition

The cottage is generally in good repair with no apparent issues.

ADDITIONAL PHOTOS

2007



2019 – East



West



South

