BELVEDERE CLUB 2019 ARCHITECTURAL INVENTORY



Site: 122 Historic Name N/A

Year Builtc. 1890Architectural StyleStick Style with Prairie addition

The north portion of this cottage appears to be the original section. The original gable front roof has been changed to a mansard, and the porch columns have been changed, giving this portion of the house more of a Second Empire style. The south portion of the cottage is typical Prairie style with its broad clapboard siding at the first floor, shingle siding at the second floor, and shallow hip porch roof with exposed rafter tails. The clapboard sided knee wall surrounding the wrap around porch with its square pillars are also typical of the Prairie style.

Significant Features

- Cross gable roof on the south portion with the second floor overhanging the first floor creating sleeping porches in the upper level.
- Wide clapboard siding at the first floor and shingle siding at the second floor.
- Wrap around porch with clapboard sided knee wall, square pillars, and shallow hip roof with exposed rafter tails.

Condition

The cottage appears to be in good repair.

BELEVEDERE CLUB 2019 ARCHITECTURAL SURVEY

ADDITIONAL PHOTOS

1892



2019 - East



BELEVEDERE CLUB 2019 ARCHITECTURAL SURVEY

South



North



BELEVEDERE CLUB 2019 ARCHITECTURAL SURVEY

West and north

