BELVEDERE CLUB 2019 ARCHITECTURAL INVENTORY



Site: 233 Historic Name N/A – moved from site 127, unknown date

Year Built c. 1905

Architectural Style Craftsman

This two-story cottage has many Craftsman style features including the beveled clapboard at the first floor and shingle siding at the second, has low, horizontal massing, the clipped gable ends come off a central hip roof. The wrap around front porch has a knee wall supporting thick Doric columns, the knee wall was originally shingle clad, typical of the Craftsman style. The angled walls at the first floor, and second floor porch with the shingle clad knee wall supporting Doric columns contribute to the character of the cottage.

Significant Features

- Central hip roof with clipped gable roofs projecting off all four sides. The gable roofs have shed roof wall
 dormers.
- Beveled clapboard siding at the first floor, shingle siding at the second floor.
- Wrap around front porch with Doric columns on paneled pillars. Second floor porch with shingle sided knee wall and Doric columns.
- Angled walls at first floor in front, double entrance doors, and tall, narrow window openings.

Condition

The cottage appears to be in good repair with no apparent issues.

ADDITIONAL PHOTOS

1907



2019 – East



East



West



North

