BELVEDERE CLUB 2019 ARCHITECTURAL INVENTORY



Site: 513 Historic Name N/A

Year Built c. 1900

Architectural Style Shingle style

The front gambrel roof with clipped gables at the front and rear of the house and full width front porch with shallow pitched roof supported by Doric columns, along with the multi-pane windows are indicative of the Shingle style. The first floor has narrow clapboard siding, the upper floor likely had wood shingles but has been replaced with wide artificial shingle siding.

Significant Features

- Front gambrel roof with clipped gables at the front and rear.
- Full width front porch with shallow pitch roof supported by Doric columns.
- Narrow clapboard siding at first floor.
- Multi-pane windows.

Condition

The cottage appears to be in good repair, no apparent issues.

ADDITIONAL PHOTOS – 1973 drawing



2019 - South and east



West and south



West and north

